

Free Fatty Acid Monitoring Strips

Introduction

Ensuring adequate quality base feed stock is the key to successful biodiesel production.

By collecting or taking delivery of poor quality oil, there will be a yield loss once the Free Fatty Acids (FFA) have been removed. Most biodiesel producers purchase WVO by weight, so if there is a high FFA level it is not in your best interests to take delivery.

Any biodiesel above 5% FFA content may be difficult to process into biodiesel without special pretreatment processes. These test strips will allow you gauge the FFA level of incoming feedstocks.

Instructions

- Simply dip the test strip into your oil and submerge for 2 seconds.
- Remove the strip and count the number of bands without any blue color. A band with blue patches is considered a blue band.
- Use the chart at the right to help determine the Free Fatty Acid level


Features

- Essential for monitoring incoming feedstocks
- Enable you to negotiate WVO prices accordingly



Part Number: BML-FFA

What's Included: Box of 40 FFA percentage level indicator strips (>2% to >7%)



1
2
3
4

FFA % $\geq 2\%$ $\geq 3.5\%$ $\geq 5.5\%$ $\geq 7\%$

Schroeder
INDUSTRIES

580 West Park Road | Leetsdale, PA 15056
ph. 724.318.1100 | fax 724.318.1200